
2025/10/14 11:00:12

506-23 TC [T4F 55kW] > F150-30-1 DRIVE HEAD ASSEMBLY 458/M1916/3



| | | |
|---|---|---|
| 0 | Not for sale | Drawing location |
| A | 458/M1916 | Drivehead<br>Supersession > |
| 1 | 448/17401 | Casing drivehead<br>< Supersession |
| 2 | 907/09000 | Bearing Roller<br>< Supersession<br>PINION HEAD |
| 3 | 921/01900 | Kit-shim<br>< Supersession |
| 4 | 921/53300 | Kit-spacer<br>< Supersession |
| 5 | 907/09100 | Bearing Taper Roller<br>PINION TAIL |
| 6 | 904/20172 | Seal Triple Lip<br>< Supersession<br>55 X 80 X 10 |
| 7 | 458/20894 | Yoke Coupling - 1480 No Flinger<br>< Supersession |
| 8 | 826/M7635 | Nut Stake M30 x 2<br>< Supersession |
| 10 | 826/01084 | Bolt M10x25 /1.50<br>< Supersession<br>NEDSCHROEF 12.9 |
| 11 | 458/M1762 | Gear Crownwheel & Pinion 8T/35T |
| 12 | 907/09200 | Bearing Taper Roller<br>DIFFERENTIAL |
| 13 | 448/05405 | Nut Side Diff |
| 14 | 826/00818 | Pin Tension |
| 15 | 448/42210 | Differential Assy |

| | | |
|---|---|---|
| 16 | 4003/2000 | Grease High Pressure<br>> No Longer Available |
| 18 | 448/56160 | Trunnion Mounting Assembly<br>< Supersession<br>DRIVEHEAD |

*Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.*